

G-code / M-code Quick Reference

Code	Description
G00	Rapid traverse
G01	Linear interpolation
G02/G03	Circular interpolation
M03	Spindle on CW
M05	Spindle stop
M08	Coolant on

Printable reference for planning and shop-floor cross-checking.